



Fluorescent Spray paint

Basic Uses: interior/exterior surfaces

SPRAY PAINT



TECHNICAL DATA

VISCOSITY: 15-20 seconds (Ford cup #4)
FLASH POINT: Less than 156°F
WEIGHT/GALLON: 8.30 ± 0.5 lbs./gal
DRYING TIME: 20 min. max.

SIZES

11 ounces can

FINISH

Flat

COLOR

Yellow
Orange
Pink
Green

DESCRIPTION

Harris Spray Paint is quick drying interior/exterior enamel that gives a durable protective finish and can be used on metal, wood or almost any other surfaces, indoor or outdoor.

APPLICATION

SURFACE PREPARATION

Thoroughly clean all grease, oil, dirt, wax and rust scale from surface before painting.

NEW METAL SURFACES: New or rusted areas should be primed with Aerosol Primer before painting. Brilliance of product may diminish after a few months of exterior exposure, requiring an additional application to restore fluorescent appearance.

PREVIOUSLY PAINTED SURFACES:

Make sure surface is free of dirt, grease, wax and rust scale from surface before painting. Use drop cloth or newspapers to protect surrounding areas from spray mist. Surface temperature must be above 65°F from painting. Do not paint in high winds or excessively high humidity.

SURFACES IN GOOD CONDITIONS:

Spray directly on bare areas. Primers

are not necessary.

SURFACES IN POOR CONDITIONS:

Remove all rust and peeled or blistered paint to restore back to sound surface. Primed all surfaces with Spray Primer, allow 30 min. to dry.

APPLICATION: Shake can until agitator ball begins to rattle and continue to shake for one min. after. Occasionally shake during use. Hold can 12 to 16 inches from surface to be sprayed and apply several thin coats rather than one heavy coat. Recoat after one hour.

PRECAUTIONS

CAUTION! Combustible. HARMFUL IF INHALED

Keep away from heat and open flame. Avoid prolonged contact with skin and breathing of vapor or spray mist. Close container after each use. Use with adequate ventilation.

Do not take internally.

KEEP OUT OF THE REACH OF CHILDREN.